CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT SECRET		tional Defense of the United States, within the meaning of Title 18, Sections 783 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.	
COUNTRY	Indochina	REPORT NO.	25X
SUBJECT	Condition of Airfields in	DATE DISTR.	30 June 1953
	Laos 25X1	NO. OF PAGES	1
DATE OF IN	NFO.	REQUIREMENT NO.	25X
PLACE ACQ	UIRED	M WILLIAM	
·	<u> </u>	V WAIBLE	
	THE APPRAISAL C	S IN THIS REPORT ARE DEFINITIVE. DF CONTENT IS TENTATIVE. KEY SEE REVERSE)	
25/1	Landing at the Xieng Khouang airs the runways are wet an impossible pierced steel board landing mate although the supplies are on the is breaking up. Bomb craters were observed there.	e task because of the slippery s. The mats are not fully laid ground. The south end of Gia L	surface of the at this field am airstrip
25X1			
, · · <u>-</u>			

25X1

STATE X ARMY X NAVY X AIR X FBI AEC

5